

INSPECTION REPORT
Sedimentation Structure
N10-A
Kayenta Mine
Navajo County, Arizona
for
PEABODY COAL COMPANY



Dames & Moore
10139-011-22

TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION	1
INSPECTION	1
SITE DESCRIPTION	2
LAND USE	2
EMBANKMENT	2
ANALYSES	3
STABILITY	3
HYDROLOGY	3
HYDRAULICS	4
Spillway Channel	6
Outflow Channel	6
STORAGE CAPACITY	6
REMEDIAL COMPLIANCE PLAN	8
GEOTECHNICS	8
HYDRAULICS	8
APPENDIX A - INSPECTION CHECK LIST	
APPENDIX B - HYDROLOGY AND HYDRAULIC CALCULATIONS	

INTRODUCTION

Sedimentation Structure N10-A is an earthen embankment, designed and constructed in 1982 by Peabody Coal Company as a temporary sedimentation structure to control runoff and sediment from the disturbed mining areas of the Kayenta Mine. The location of Structure N10-A is shown on Plate 1, Site Plan.

This inspection report contains information specific to Structure N10-A. Regional site information is presented in the "General Report, Kayenta and Black Mesa Mines, Navajo County, Arizona for Peabody Coal Company," along with the methods and results of analyses used for slope stability, hydrology and hydraulics.

INSPECTION

Structure N10-A was inspected on September 7, 1985 by an interdisciplinary team of engineers from Dames & Moore. The purpose of the inspection was to assess the safety and general condition of the structure with respect to United States Department of Interior, Office of Surface Mining (OSM) regulations.

Dames & Moore's inspection was performed in accordance with applicable 30 CFR 780 and 816 regulations and included a review of the N10-A project files and a field inspection of the structure. The most current information contained in the Peabody Coal Company files includes maps

developed in 1985 by Peabody Coal Company, which were used in the analyses of the structure. Results of the field inspection are included in this report as Appendix A.

SITE DESCRIPTION

LAND USE

Structure N10-A has a 625.1-acre tributary drainage area and is located near Coal Mine Wash at the Kayenta Mine. The watershed is classified as 60% Pinion/Juniper, 35% reclaimed, and 5% Sagebrush/grass.

EMBANKMENT

Structure N10-A is a homogeneous earthen embankment classified as a cross-valley embankment. Physical characteristics of the embankment are listed in the following table:

Structure N10-A

Embankment	Mine Waste
Foundation	Sandstone
Right Abutment	Residual Shale Soils
Left Abutment	Mine Waste
Height	14.6 ft
Crest Width	15 ft
Upstream Slope	4.0 H : 1 V
Downstream Slope	3.5 H : 1 V

A cross-section of the embankment is shown on Plate 2, Existing Maximum Cross Section N10-A, A-A'.

ANALYSES

STABILITY

Structure N10-A is an embankment that does not fit into the eleven categories outlined in the "General Report". Since extensive reconstruction is necessary to correct deficiencies found during the inspection and the hydrologic and hydraulic analyses, a stability analyses was not performed at this time. During reconstruction the embankment material can be classified, the structure placed into its proper category and safe slopes selected.

HYDROLOGY

The hydrologic analysis was completed using the U.S. Army Corps of Engineers generalized computer program HEC-1, Flood Hydrograph Package. Structure N10-A is located upstream from Structures N10-A1 and N10-A2. The three structures have a combined storage capacity that is greater than 20 acre-feet. However, the spillway for N10-A was analyzed using the 25-year, 6-hour storm because the structure is located upstream of the others. The storage capacity of Structure N10-A was analyzed using the 10-year, 24-hour storm.

The following parameters were used in the hydrologic analysis:

1. Water Course length, L	1.69	mi
2. Elevation Difference, H	500	ft
3. Time of Concentration, T	0.435	h
4. Lag time, $0.6T_c$	0.261	h
5. SCS Curve Number	83	
6. Rainfall Depth, 10-year, 24-hour storm .	2.1	in.
25-year, 6-hour storm. .	1.9	in.
7. Drainage Area	625.1	acres

HYDRAULICS

The HEC-1 program was used to evaluate inflow to the sedimentation structure, outflow from the structure and the resulting water surface elevations. The initial conditions and results of the analysis are summarized in the following table.

N10-A HYDRAULICS

	Units	10-year 24-hour Storm	25-year 6-hour Storm
Initial Reservoir Volume			
Condition		Empty	Full to the spillway elevation
Inflow			
Peak Flow	cfs	486	544
Volume	acre-ft	39.1	30.7
Storage			
Peak Stage	ft	6688.32	--
Peak Storage	acre-ft	--	--
Storage Capacity . . .	acre-ft	14.0	--
Outflow			
Peak Flow	cfs	213	481
Embankment Crest			
Elevation	ft	--	6690.40
Peak Stage	ft	--	6689.40
Freeboard	ft	--	1.0
Spillway Channel			
Flow Depth	ft	--	3.4
Critical Velocity. . .	fps	--	7.2
Manning's "n"		--	0.040
Outflow Channel			
			<u>Section I</u> <u>Section II</u>
Slope	%	--	6 23
Normal Velocity. . . .	fps	--	10.4 15.9
Normal Depth	ft	--	1.37 0.92
Manning's "n"		--	0.040 0.040

Spillway Channel

The structure presently has no spillway.

Outflow Channel

The structure presently has no outflow channel.

STORAGE CAPACITY

The impoundment volume-elevation curve is based on site specific surveys conducted for Peabody Coal Company's August 1984 inspection, and 1985 resurveys, where available. Additionally, the most current topographic maps available were used in developing Plate 3, Volume-Elevation Curve, N10-A.

The calculations for the sediment load entering Structure N10-A were made utilizing the Universal Soil Loss Equation with the following parameters:

1. Rainfall Factor, R 40
2. Soil Erodibility Factor, K 0.271
3. Slope Factor, LS 7.13
4. Cover Factor, C 0.156
5. Erosion Control Factor, P 1.0

The hydrologic analysis gives the storage volume required to contain the 10-year, 24-hour storm, and the remaining storage volume available for storing sediment. The existing storage capacity of N10-A and the results of the sediment inflow analysis are summarized in the following table.

N10-A STORAGE

Total Storage Capacity	14.0	acre-ft
10-year, 24-hour Storm Inflow	39.1	acre-ft
Available Sediment Storage Capacity . .	0	acre-ft
Sediment Inflow Rate	3.31	acre-ft/yr
Sediment Storage Life	0	yrs

Although Structure N10-A does not have any sediment storage capacity by itself, there are two structures downstream which operate in series with N10-A. Therefore the combined sediment storage capacity was analyzed. The following table summarizes the results.

COMBINED STORAGE FOR N10-A, N10-A2, AND N10-A1

	<u>N10-A</u>	<u>N10-A2</u>	<u>N10-A1</u>	<u>Total</u>	
Total Storage Capacity	14.00	24.59	12.20	50.79	acre-ft
10-year, 24-hour Storm Inflow	39.10	2.50	0.98	42.58	acre-ft
Available Sediment Storage Capacity . .	—	—	—	8.21	acre-ft
Sediment Inflow Rate	3.31	0.528	0.238	4.08	acre-ft/yr
Sediment Storage Life	0	—	—	2.0	yrs

REMEDIAL COMPLIANCE PLAN

GEOTECHNICS

The inspection of Structure N10-A indicated that geotechnical problems consist of rill erosion on the upstream and downstream slopes and a 30-foot-long crack on the crest and downstream slope of the embankment near the left abutment. Correction of erosion is considered a periodic maintenance task and does not require remedial action. Extensive reconstruction of the embankment is recommended to repair the cracking evident near the left abutment. At that time the embankment can be classified and safe slopes selected.


HYDRAULICS

Structure N10-A has sufficient storage capacity but it does not have a spillway or outflow channel. A trapezoidal spillway channel should be constructed at elevation 6686.0 feet. A trapezoidal outflow channel with the same bottom width as the spillway should be constructed along the alignment shown in Plate 1. The spillway, outflow channel and stilling basin profile is shown in Plate 4 and the required dimensions are shown in Plate 5 and Plate 6. Both the spillway and outflow channel should be protected against erosion using geotextile and riprap as shown in Plate 5.


* * *

The following plates and appendix are attached and complete this inspection report.

- Plate 1 - Site Plan N10-A
- Plate 2 - Existing Maximum Cross Section N10-A, A-A'
- Plate 3 - Volume-Elevation Curve N10-A
- Plate 4 - Channel Profile N10-A, B-B'
- Plate 5 - Spillway and Outflow Channel Cross Section N10-A
- Plate 6 - Spillway Stilling Basin Plan N10-A
- Appendix A - Inspection Check List
- Appendix B - Hydrology and Hydraulic Calculations



SITE PLAN
N10-A




EXISTING
MAXIMUM CROSS-SECTION
A-A'
N10-A


FOR LOCATION SEE PLATE 1

BY **Dames & Moore**

Plate 2



VOLUME-ELEVATION
CURVE
N10-A




CHANNEL PROFILE B-B'
N10-A



FOR LOCATION SEE PLATE 1

BY **Dames & Moore**

Plate 4



SPILLWAY CHANNEL

$D = 4.4'$


LENGTH = 40'

FLOWLINE ELEV. = 6686.0'

OUTFLOW CHANNEL

$D = 2.5'$

**SPILLWAY AND
OUTFLOW CHANNEL
CROSS SECTION
N10-A**



MINIMUM HEIGHT OF RIPRAP
ALONG SIDEWALLS ABOVE
THE BASIN FLOOR = 7.8'

MINIMUM DEPTH OF BASIN FLOOR
BELOW NATURAL STREAMBED = 4.2'

SPILLWAY STILLING BASIN PLAN N10-A

APPENDIX A
INSPECTION CHECK LIST

INSPECTION CHECK LIST

ITEM	YES	NO	REMARKS
1. CREST			Rounded $\approx 15'$ w.
a. Any visual settlements?		X	
b. Misalignment?		X	
c. Cracking?		X	
2. UPSTREAM SLOPE			14°
a. Adequate grass cover?		X	
b. Any erosion?	X		Rills
c. Are trees growing on slope?		X	
d. Longitudinal cracks?		X	
e. Transverse cracks?		X	
f. Adequate riprap protection?		X	
g. Any stone deterioration?		X	NA
h. Visual depressions or bulges?		X	
i. Visual settlements?		X	
j. Animal burrows?		X	
3. DOWNSTREAM SLOPE			16°
a. Adequate grass cover?		X	
b. Any erosion?	X		Rills
c. Are trees growing on slope?		X	
d. Longitudinal cracks?		X	
e. Transverse cracks?	X		30' long crack near LA
f. Visual depressions or bulges?		X	
g. Visual settlements?		X	
h. Is the toe drain dry?			NA
i. Are the relief wells flowing?			NA
j. Are boils present at the toe?		X	
k. Is seepage present?	X		below toe
l. Animal burrows?		X	
4. ABUTMENT CONTACT. RIGHT			
a. Any erosion?		X	
b. Visual differential movement?		X	
c. Any cracks noted?		X	
d. Is seepage present?		X	
e. Type of Material?			Reclaimed F.I.
5. ABUTMENT CONTACT. LEFT			
a. Any erosion?		X	
b. Visual differential movement?		X	
c. Any cracks noted?		X	
d. Is seepage present?		X	
e. Type of Material?			Gray Silty & rock

ITEM	YES	NO	REMARKS
6. SPILLWAY/NORMAL			No Spillway
a. Location:			
Left abutment?			
Right abutment?			
Crest of Embankments?			
b. Approach Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
c. Spillway Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
d. Outflow Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
e. Weir:			
Condition?			
7. SPILLWAY/EMERGENCY			
a. Location:			
Left abutment?			
Right abutment?			
Crest of Embankments?			
b. Approach Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
c. Spillway Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
d. Outflow Channel:			
Are side slopes eroding?			
Are side slopes sloughing?			
Bottom of channel eroding?			
Obstructed?			
Erosion protection?			
e. Weir:			
Condition?			

ITEM	YES	NO	REMARKS
8. IMPOUNDMENT			
a. Sinkholes?			(Elev.) feet
b. Water present?	<input checked="" type="checkbox"/>		(Elev.) feet
c. Siltation?			?
d. Watershed matches soil map?		<input checked="" type="checkbox"/>	

9. GENERAL COMMENTS


Spillway should be in LA, No approach channel needed, Do need exit channel with rip rap.
 Crest rounded, slopes are to

DAM-Heterogeneous Fill with large rock & brown SM

Deep arroyo d.s. with SS outcrops vertical sides

Bottom of Arroyo near D.S. toe - water present
 Potential Seepage thru SS or thru dam.

Crack 30' Long transverse near L.A. in d.s. Slope up toward crest.



APPENDIX B
HYDROLOGY AND HYDRAULIC CALCULATIONS

UNIVERSAL SOIL LOSS EQUATION

RAINFALL FACTOR

$$R = 40$$

SOIL ERODIBILITY FACTOR

SOIL TYPE =

35% EM #35	(.35)(.42)
50% EM #30	(.5)(.44)
15% EM #27	(.15)(.36)
	<u>0.271</u> ✓

$$K = \underline{0.271}$$

SLOPE FACTOR

LENGTH (ft.)	Δ ELEV (ft.)	SLOPE (%)	LS
1700'	135	7.9	4.03 2.97 (.3)
600'	125	20.8	10.9 5.97 (.3)
600'	80	13.3	5.05 4.27 (.2)
1400'	80	5.7	2.30 1.76 (.1)
500'	180	22.5	14.1 11.50 (.1)
			<u>7.13</u> <u>5.76</u>

COVER FACTOR

AREA (ac.)	COVER TYPE	% COVER	CANOPY (%)	WEIGHTED C
35%	reclaimed	—	—	.15(.35)
60%	P-5	40	25	.60(.14)
15%	S-6	40	25	.15(.13)
				<u>0.156</u> ✓

EROSION CONTROL FACTOR

$$P = 1.0$$

SEDIMENT INFLOW

$$A = 40 (.271) \overset{7.13}{(5.76)} \overset{12.06}{(0.156)} (1.0) = \underline{9.74} \text{ ton/acre/year}$$

$$A = \overset{12.06}{9.74} \left(\frac{1}{2047} \right) (625.1) (.9) = \overset{3.31}{2.64} \text{ acre-feet/year}$$

Dames & Moore

REVISIONS

BY DATE TO DO
 BY DATE TO DO

BY DATE

CHECKED BY BHM-11/11/85

COPY TO DO

TIME OF CONCENTRATION

ELEVATION DIFFERENCE = $700' - 6670 = 500'$ ✓

WATER COURSE LENGTH = $8.900' = 1.69 \text{ mi}$ ✓

$T_c = 0.4433 \cdot 435$

Lake Time = $0.6 T_c = 0.266$

.261

SCS CURVE NUMBER

DRAWAGE AREA (ac)	COVER TYPE	HYDROLOGIC CONDITION	SOIL TYPE	WEIGHTED CURVE NUMBER
220.8	reclaimed (pre-law)	poor	—	87 (.35)
375.3	P-J	ave	D	83 (.60)
29.0	S-G	ave	B	60 (.05)
				<u>83.25</u> ✓
				use <u>83</u>

DRAINAGE BASIN AREA

625.1 ACRES

0.977 SQ. MILES ✓

REVISIONS

BY _____ DATE _____ TO DO _____
 BY _____ DATE _____ TO DO _____

BY 10/1/85 DATE 10/1/85

CHECKED BY BHM 11/11/85

COPY TO DO